

管理番号：0636103

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	無	点傷有

◎：良好
○：通常走行問題なし
△：要修理
／：装備無し
※あくまでも当社判断基準によるものです

エンジン		
点検項目	結果	状態
異音	◎	
オイル混入	◎	
オイル漏れ	○	ロッカーケース、 オイルパン しみ
水混入	◎	
水漏れ	◎	
燃料漏れ	◎	
排気	◎	
マフラー	◎	
ターボ	◎	
冷却水吹返	◎	

ミッション		
点検項目	結果	状態
ギア鳴き	◎	
ギア抜け	◎	
クラッチ	◎	
異音	◎	
オイル漏れ	◎	
リターダ	／	

電装関係		
点検項目	結果	状態
エアコン	◎	
スターター	◎	
オルタネーター	◎	
P/W（運転席）	◎	
P/W（助手席）	○	下降時キー音（小）
坂道発進装置	◎	
異常ランプ	◎	
オーディオ	◎	
バックカメラ	△	映らない
電格ミラ	◎	
ETC	◎	標準
タコグラフ	／	

上物仕様		
点検項目	結果	状態
床材質	／	アルミ キーストン

キャビン		
点検項目	結果	状態
シート	◎	
ヘッドライト	◎	ハロゲン
ウィンカー	◎	
ワイパー	◎	
ミラ	◎	

走行関係		
点検項目	結果	状態
リーフサス	◎	
エアサス	／	
パワステ	◎	
ハンドル	◎	
燃料タンク	◎	スチール 100L

デフ		
点検項目	結果	状態
異音	◎	
オイル漏れ	◎	
デフロック	／	

特記事項 エンジンキー1本、ドアロックリモコン付きエンジンキー1本、ボテキー4本（リヤ固着・サイドOK）、リアステップ曲り

記録簿 無 ()

タイヤ残量

単位：mm

4

3

—

—

4

3

3

2

—

—

—

—

スベア

9

—

タイヤサイズ

205/70R16

205/70R16

—

—

205/70R16

205/70R16

205/70R16

205/70R16

—

—

—

—

スベア

205/70R16

—

素材：スチール

備考：

Figure 1 shows the front and side views of a truck with a grid overlay. The front view shows a truck with a grid. The side view shows a truck with a grid. Labels indicate damage areas: "外装キズ" (Exterior Scratch) on the front bumper, "外装へこみ" (Exterior Dent) on the hood, "外装キズ" (Exterior Scratch) on the side door, "外装へこみ" (Exterior Dent) on the side door, "庫内へこみ" (Interior Dent) on the side door, and "割れ" (Crack) on the rear wheel.

【外装】

【ボデー内】

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------