

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	中	点傷有

Figure 1 consists of two line drawings of a truck on a grid background. The left drawing is a front view showing damage labels: '歯がり' (chigari) on the lower left bumper, '外装キズ' (gaishō kizu) on the upper right and lower right of the front panel, and '外装キズ' (gaishō kizu) on the right side mirror. The right drawing is a side view showing damage labels: '外装キズ' (gaishō kizu) on the front fender, '外装キズ' (gaishō kizu) on the rear of the cargo box, and '外装キズ' (gaishō kizu) on the lower side of the chassis.

【外装】				【ボデー内】						
外装キズ	外装へこみ	うき	曲がり	サビ	補修跡	割れ	庫内キズ	庫内へこみ	庫内穴あき	床汚れ