

外装状態			
キャブコーション	フレーム番号	フレームのさび	飛石
有	確認済	大	飛石有(リペア可)

エンジン		
点検項目	結果	状態
異音	◎	
オイル混入	◎	
オイル漏れ	○	オイルパン、 パワステオイルポン プ
水混入	◎	
水漏れ	◎	
燃料漏れ	◎	
排気	◎	
マフラー	○	腐食
ターボ	/	
冷却水吹返	◎	
ミッション		
点検項目	結果	状態
ギア鳴き	◎	
ギア抜け	◎	
クラッチ	◎	
異音	◎	
オイル漏れ	◎	
リタージ	/	

電装関係		
点検項目	結果	状態
エアコン	◎	
スターター	◎	
オルタネーター	◎	
P/W（運転席）	◎	
P/W（助手席）	△	動かない
坂道発進装置	/	
異常ランプ	◎	
オーディオ	△	音出ない、操作不良 アンテナ折れ
バックカメラ	/	
電格ミラー	△	動き悪い
ETC	/	
タコグラフ	◎	アナログ
上物仕様		
点検項目	結果	状態
床材質	/	鉄板

キャビン		
点検項目	結果	状態
シート	○	破れ、へたり
ヘッドライト	◎	ハロゲン
ウィンカー	△	サイド：左不灯
ワイパー	◎	
ミラー	◎	
走行関係		
点検項目	結果	状態
リーフサス	◎	
エアサス	/	
パワステ	◎	
ハンドル	○	擦れ
燃料タンク	◎	スチール 300L
デフ		
点検項目	結果	状態
異音	◎	
オイル漏れ	◎	
デフロック	/	

記録簿 無 ()

The image shows two line drawings of a truck on a blue grid background, intended for a labeling exercise. The left drawing is a front view of the truck. It has four 'サビ' (Rust) labels along the top edge of the windshield and two '曲がり' (Bent) labels on the front bumper. The right drawing is a side view of the truck. It has two '外装へこみ' (Exterior dent) labels on the cab and five 'うき' (Sinking) labels along the top edge of the cargo box.

The left diagram shows a 3x4 grid of 'サビ' (Rust) components. The right diagram shows a vehicle chassis with 'うき' (Fenders) and '外装キズ' (Exterior Damage) components.

【ボデー内】

外装 キズ	外装 へこみ	うき	曲がり	サビ	補修跡	割れ	庫内 キズ	庫内 へこみ	庫内 穴あき	床 汚れ
----------	-----------	----	-----	----	-----	----	----------	-----------	-----------	---------